

DRŤ	mm	2,800	2,360	2,000	1,700	1,400	1,180	1,000	0,710	0,425	0,300	0,180	0,125	0,075
SAE	7	8	10	12	14	16	18	20	25	30	35	40	45	
G10		AP		MIN 80 %	MIN 90 %									
G12			AP		MIN 80 %	MIN 90 %								
G14				AP		MIN 80 %	MIN 90 %							
G16					AP		MIN 75 %	MIN 85 %						
G18						AP		MIN 75 %	MIN 85 %					
G25							AP		MIN 70 %	MIN 80 %				
G40								AP		MIN 70 %	MIN 80 %			
G50									AP		MIN 65 %	MIN 75 %		
G80										AP		MIN 65 %	MIN 75 %	
G120											AP		MIN 60 %	MIN 70 %